SEPA POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION REGION 100 23			
NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.			
A. SITE NAME	B. STREET (or other identifier)		
Technicon Electronic Corp. Site	Road No. 3 Km. 77.4		
Humacao	P. R.	00661	Humacao
G. OWNER/OPERATOR (if known)			
1. NAME			
Sidney Hershey 809) 852-1035			
☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☐ 5. PRIVATE ☐ 6. UNKNOWN			
I. SITE DESCRIPTION			
Industrial wastes water discharge to a nearby creek Quebrada Frontera.			
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)  K. DATE IDENTIFIED			
Agencies file			5-1-81 yr.)
L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM		* .	
1) - Discharge liquid wastes to Quebrada Fronteras			
2) - Mercury contents on wastes stream			<b>-</b>
3) Enforcement action being taken for several years.			
4) Affected persons with Mercury have taken civil court action in this case.			
		•	
OML			
M. PREPARER INFORMATION  1.2. TELEPHONE NUMBER  3. DATE (mo., day, & yr.)			
Jaime L. Ortiz, Project Director		5-5140	5-1-81

to Secretarian Comments to the secretarian

DECLASSIFIED

Date: Initial: TD

407519